

Part Number

Description

Box Part Number Dimension

Other Packaging Dimension

Logo Decals

Packaging Instructions and Decal Placement

D109-739-013

Tape box securely. Put foam at bottom of box and add paperwork. Put lock in box. Add foam to prevent movement. Close box. Apply Dart logo tape. Apply label D2729-3 as per instructions in QSI 014. On the D2729-3 label, mark the number on the key record, with a fine black permanent marker.

D2729-4

N/A

D2729-3



Revision: A

Date: 13.01.28

H:\Admin-q\liso\forms\PPP-1.Rev.A